

Operations at the oil well were brought to a stop some time ago by the breaking of a crank shaft on the engine. It may be several weeks before work is resumed.