

John T. Johnson's threshing engine blew up on Tuesday morning while at work on the farm of John Hanchett six miles south of McHenry. Henry Ehlert was killed and several members of the threshing crew were injured. The cause of the explosion is not known but the affair is being investigated.