

During the thunder storm of Saturday afternoon the large barn of Albert Kokatt six miles north of Jamestown was struck by lightning and a hole torn in the roof, beams splintered and other damage done. No fire was started and stock in the barn was not injured. The hole in the roof was large enough to throw a man through.