Fine New

Barn Finished

AN UP-TO-DATE STRUCTURE NOW

STANDS ON THE F. B.

WEBBER FARM

One of the most up-to-date barns to be found is the one just completed on the F. B. Webber farm, north of Courtenay, which can be seen for quite a distance in every direction and has been

y

e

e

1

е

t

h

can be seen for quite a distance in every direction and has been commented upon by all who have seen the barn. The following will give one a good knowledge of the kind of a structure Mr. Webber has added to his place.

The barn is located west of the farm home, situated on a level piece of high land and is 32 feet in width and 56 feet in length. The posts from the sill to the peak are 32 feet. The roof is round. The interior of the barn has the appearance of a

S 1 comfortable home. There is double set of windows which 0 gives the barn an abundance of light. The barn stands upon a t r solid concrete foundation. The capacity of the barn is 25 e head of stock, 50 tons of hay, 400 bushels of oats. There is a room devoted for harness, e r 1 something few consider when building barns. There are box stalls with plenty of room, tank е n and hay carrier. The material used in this barn, including the

lumber, hardware, paint, and all other material, were pur-chased of Courtenay firms, and f was the best that money could t buv. y Angell & Grant had the cond tract for the painting, and gave the barn two coats. S The carpenter work was done n by Heitman & Olson of Courtey nay, and cannot be excelled by any firm in their line, which demonstrates their ability as carpenters.

carpenters.
Mr. Webber expressed himself as thoroughly satisfied with the first-class workmanship given him by the contractors.