Harry Westley, who is working as cierk and delivery boy for the Hannaford Mercantile Co., sustained a broken arm last Friday while cranking the Ford. Harry had taken care to retard the spark lever, but a cotter pin had fallen out, causing the timer to be released from the spark lever, with the result that pre-igni-it tion occurred, the handle was jerk- 1 ed back, and Harry's arm was brok- 1 en just above the wrist. Harry will o be laid up for quite a while as a result of his misadventure.